**Software Version:** N/A

Firmware Version: V22.09.23

Database Version: V22.00.11

**Bootloader Version:** V22.09.22

#### **Recommended Use**

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

### Affected Product(s)

• (0x3DF) 5160rs-5610

#### **New / Added Features & Functions**

- Support vehicle up to 2022
- New features under OEM Diagnostics:
  - Added an OEM Enhanced Live Data landing page to stream ECM and TCM.
- New and improved OBD2 Live Data PID list with quick selection to record data and submit it to the server via RS2 App.
- New expanded tool functions:
  - Added more *Active Test* and *Special Function* for the engine system
- Support 7 vehicle makes with the most function: GM, FORD, CHRYSLER, HONDA, TOYOTA, HYUNDAI, NISSAN
- Added QR Code to get even more with the RepairSolutions2 mobile app.
  - Gain free access to:
    - Vehicle Health Reports
    - Verified Fixes and Parts Required
    - Predicted Repairs
- Added tool ID

#### Fixes / Updates

- Update database and firmware to fix ABS, SRS and TPMS read DTC: 2010 Jeep Compass, 2019
  Mercedes Sprinter 3.0 V6 2500 4x4, 2005 Pontiac GTO 6.0L LS2.
- Update database and firmware to fix DPF Reset: 2015 Chevrolet Silverado 6.6, 2010 Chevrolet Express G4500s, 2017 Chevrolet SILVERADO 2500 6.6L DIESEL.
- Update database and firmware to fix Transmission Fluid Temperature: 2004 Chevrolet Trailblazer 4.2L.
- Update database and firmware to fix Battery reset: 2009 BMW 328i.

# **Product Release Notes**

Scan Tools and Code Readers

- Update database to fix ABS live data: 2007 Cadillac CTS, 3.6L.
- Update database and firmware to fix Special function/Crankshaft Pos. Variation Learn: 2008 Hummer H3.
- Update database and firmware to fix Special function/Cylinder Power Balance: 2017 Chevrolet Trailblazer L6, 4.2L.
- Update database and firmware to fix Service reset/ABS Bleeding 2010 Toyota Prius, 2006 Mini Cooper.

## **Product Support**

Please visit us at innova.com/support for additional information.